

Fejmert®

MADE IN SWEDEN



The PUCEST® PU-Tix has been developed especially to renew/repair worn out PUCEST® linings.

User-friendly 2-component filler with 15 years of proven success!

With conventional wear-linings complete segment need to be replaced.

The PUCEST® Tix saves the effort and expense, it is enough to repair the damaged area.



Immediate repair of damaged linings:

- Shortens downtime for the machine
- Simple, manual operation
- Extremely durable



PUCEST® PU-TIX

Tix kit - gives 1.6 kg of 2-component filler

Fejmert Mixer AB
Blommenhovsvägen 26
S-611 39 Nyköping, Sweden

Tel.: +46 155-582 00
E-mail: fejmert@fejmert.se
Web page: www.fejmert.se